

Chyba P0154 - ako resetovať ?

URL

<https://www.quadmania.cz/forum-detail/?ft=7821&fid=3>

Autor

TheSalon112

Publikováno: 07.07.2022 23:27:40

Dobrý deň, Dnes som prvý krát naštartoval novú X850ku (CF MOTO EU5) a po prejdení asi 10km (neprekročil som rýchlosť 30 km/h) na mňa "vybafla" chyba P0154 a od vtedy stále svieti "check engine". Nepomohlo ani vypnutie motora, ani "nechať vychladiť", ani umyť vopom :D . Stroj vyzerá, že ide ako má (keďže zabieham, jazdím len veľmi opatrne, takže možno nejaké obmedzenie je, akurát o ňom neviem). Čítal som, že to je O2 čidlo, ale pre mňa je to španielska dedina. Na internete som nenašiel ako sa takýto "check engine" resetuje, to naozaj mám ísť hneď po 10 km do servisu ? :D

Ďakujem

[manas76 09.07.2022 07:18:35](#)

Ano do servisu --- na to máš záruku.

[kabalero 09.07.2022 19:55:32](#)

Zdravím borci tak jsem na ACCESS 750 MAX vyměnil řídicí jednotku.Chvíli to bylo dobrý,ale už zase kolísá volnoběh a někdy cuká tak do 4 tisíc otáček.Je to prostě zábava vlastnit takovou značku.Neřešil jste někdo podobný problém?Dík za event.nápad.Danda.

[pája27 10.07.2022 08:52:38](#)

kabalero> Ano řešil jsem to. :-D A to výměnou za Can-Am 650. Viz můj profil.

Propálený výfuk po pár km mne dohnal k tomu kroku. Jinak by ta taivanská pomsta asi brzo shořelá celá. (n)

[helgaella99 06.02.2025 03:09:35](#)

@[Escape Road](#) Chyba P0154 často značí problém s kyslíkovým čidlom (O2 senzor). Skúste resetovať "check engine" odpojením batérie na 10 minút. Ak chyba pretrváva, návšteva servisu je najbezpečnejšia voľba.

[ponte4 09.10.2025 09:07:22](#)

Hey! Bummer about the check engine light popping up so early on your new X850. Error code P0154 definitely points to the O2 sensor, which can be a pain. It's probably worth checking the connections to the sensor first, but yeah, might be a trip to the dealer unfortunately. This makes me want to chill and play something relaxing like [Snow Rider 3D](#)! Hope you get it sorted quickly and can properly enjoy your new ride!

[Daveyhg 03.11.2025 08:10:28](#)

That sounds really frustrating, especially since the X850 is brand new and you're just

breaking it in! Sometimes electronics throw random errors—my car once did the same. If you want a quick distraction while waiting or researching (so you don't stress too much about the check engine light), I recommend playing a few levels of [Run 3](#). Hope you get the sensor issue sorted out soon!

Joros 11.11.2025 12:51:21

He estado explorando varias plataformas de juego en línea últimamente y quería compartir mi experiencia con algo que me llamó bastante la atención. Me refiero a Swiper Casino, lanzado en 2024, que se presenta como una plataforma elegante de juegos móviles con licencia bajo las regulaciones de Curacao. Desde que lo probé por primera vez, lo que más destacó para mí fue la manera en que está diseñado específicamente para dispositivos móviles. A diferencia de otros sitios que simplemente reducen la versión de escritorio, aquí se nota que la experiencia fue pensada desde cero para pantallas táctiles <https://swipercasino.es/>. Una de las características que más me sorprendió es su innovadora función de deslizamiento. Esta función no es solamente estética, realmente cambia la forma en que se navega. En vez de estar tocando botones pequeños o menús complicados, se puede desplazar y cambiar entre secciones con gestos intuitivos. Esto hace que la exploración sea más fluida y agradable, sobre todo cuando se juega desde una tableta o un teléfono. Sinceramente, es algo que muchos otros sitios deberían considerar, porque hace que todo se sienta más moderno y cómodo.

yuzhang 17.12.2025 04:26:21

It seems frustrating to encounter a "check engine" light so soon on your new X850. The issue might indeed be related to the O2 sensor, but don't stress just yet. For more tips and solutions for your vehicle, visit [bounce path](#)—your trusted guide for troubleshooting and advice!

yuzhang 17.12.2025 04:28:04

It seems frustrating to encounter a "check engine" light so soon on your new X850. The issue might indeed be related to the O2 sensor, but don't stress just yet. For more tips and solutions for your vehicle, visit [bounce path](#)—your trusted guide for troubleshooting and advice!

Leonield 11.03.2026 03:12:22

The car seems to be running fine but maybe there is a limit to the speed or power. I've seen it's something to do with the O2 sensor, which is like Martian to me. A real [Slice Master](#) mechanic friend could probably work it out. Can't find anything online about how to reset the check engine light on this model; does it really need a trip to the mechanic? This reminds me of that time when my laptop completely froze at a crucial moment right before a presentation.

Yasminoyce 16.03.2026 08:55:01

Diagnosing such a code without the right tools feels like navigating a maze blindfolded. This often points to a mischievous oxygen sensor issue, a truly [Level Devil](#) of a problem. I once wrestled with a similar phantom P-code on an older pickup. It was a maddening hunt for a faulty sensor, causing erratic idling and poor fuel economy.